FIRMWARE 2.01 RELEASE NOTES

OVERVIEW

Minor changes from 2.00.

Refer to the 2.00 Release Notes if you are currently upgrading from 1.xx firmwares. This only describes changes from the previous version.

FULL CHANGES

1. Improved SD controller compatibility. Cards that previously failed to boot resulting in a black screen may now work properly. Added proper speed detection.
2. Made Pokemon Stadium 2 save fix fully transparent to the console.
3. Fixed stability problem in USB mode with no N64 connected on some units.

HOW TO UPGRADE

First, check to see what firmware version you currently have, by opening the "About" tab in the 64drive menu.

- **You have 1.00-1.05:**
  You must upgrade using the **Easy Upgrader**, or the **command line USB Loader 1.xx** tool.
  Refer to the 2.00 Release Notes for instructions on how to use the command line tool.

- **You have 2.00:**
  Simply copy the "64drive_firm_201.rpk" file from the website onto your memory card.
  Load the file in the menu as if you were starting a game, and your firmware will be upgraded.
  You should have at least Menu 1.12c for this method.

  Alternatively, you can use the command line USB Loader 2.xx tool to upgrade via USB.

END OF DOCUMENT

REVISION INFORMATION

April 27, 2015	First internal draft
May 6, 2015	Current internal revision

COPYRIGHT INFORMATION

© 2011-2015 Marshall H / Retroactive
http://64drive.retroactive.be/

"Nintendo" is a registered trademark of Nintendo of America Inc.
Nintendo 64 is a registered trademark of Nintendo Company, Limited

This product is not endorsed or supported by Nintendo. Use the device at your own risk.

To submit any inaccuracies or inconsistencies in this document, please e-mail support at the above web address.